

EMERGENCY RESPONSE OPERATING RECORD
(40 CFR 265.56)

470678

This record is to be filled out by Primary Emergency Coordinator or his designee.

REPORTED BY: Rocky Miller, SupervisorA. Date of Incident: October 6, 1986B. Time of Incident: Approximately 7:00p.m.C. Type of Incident: (circle one) Fire, Spill, Explosion.

D. Hazardous Material(s) involved:

<u>Name</u>	<u>Quantity (lbs, gal)</u>
-------------	----------------------------

Trichlorethylene

20 gallons

E. Extent of injuries (if any).

None

F. Assessment of actual or potential hazards to human health or environment. (To be filled in by Safety Manager).

None to human health or environment.

G. Estimated quantity and disposition of recovered material that resulted from incident. (To be filled in by Hazardous material Engineer).

2/3 drum filled with dirt and absorbant. Send to secure landfill.


H. Notification of Regional Administrator, State and Local Authorities that the Facility is in compliance with 40 CFR 265.56 (h), (1), (2) before operations are resumed in affected area(s) of Facility. (Hazardous Material Engineer).

The release was contained and cleaned up. There was no release to air,

CONTINUED ON BACK OF PAGE.

Emergency CoordinatorHazardous material EngineerJohn T. Fitcham
Safety Manager 10/17/86

H Continued: water or sewer. There was a release to the ground (approximately 9 square feet) of approximately 1 gallon. This dirt was scooped up and placed with the absorbant. Since there was no release that could threaten human health or the environment outside the facility (320 IAC 4.1-18-7(d), the Emergency Response Center was not notified. The spill was contained and emergency equipment is fit for its intended use. 320 IAC 4.1-18-7(h), (1), (2) and (i). (see below)



SPILL SITE